



Ground zero.

D4 center point to ground zero.

Centering point of holes is the physical center of every lead on the connector (pin-out & shield pegs)